

Visual differences of the tensioning pulley 531 0280 10

Manufacturer:

Fiat, Lancia

Model:

- **Fiat** Brava, Bravo, Doblo, Marea, Multipla, Palio, Siena, Stilo
- **Lancia** Dedra, Delta II, Lybra

Engine:

1.6 16V

LuK AS Part No.: 531 0280 10

OE-No.:

7173 4799

4641 6489 (replaced)
4679 2898 (replaced)

For the models listed above, two different tensioning pulleys can be fitted.

Note:

Both tensioning pulley types are approved by the vehicle manufacturer.



Fig. 1: OE-Type


Fig. 1 shows the tensioning pulley installed by the vehicle manufacturer as standard.

This tensioning pulley is also supplied by **LuK AS** in the spare parts market.



Fig. 2: OES-Type

Fig. 2 shows the tensioning pulley from the vehicle manufacturer replacement part range.

 Assembly and adjustment of the toothed belt tension must be carried out in accordance with the instructions provided by the manufacturer.

Appropriate spare parts can be found in our on-line catalogue at www.Schaeffler-Aftermarket.com or at www.RepXpert.com.

Issued 11.2007

INA 0010

Technical subject to change

© 2007 LuK-Aftermarket Service oHG

For further information:

Phone: +44 (0) 14 32 264 264*

Fax: +44 (0) 14 32 275 146

Info@LuK-AS.co.uk

www.Schaeffler-Aftermarket.com

* Calls from within the UK 08457 001100

