



LuK Service Info



Concentric slave cylinders 510 0088 10 and 510 0164 10

Different size hydraulic connections

Manufacturers: Dacia
Nissan
Renault

LuK part no.: 510 0088 10
510 0164 10



Fig. 1: Concentric slave cylinders with small hydraulic connections

In vehicles made by the manufacturers listed above, concentric slave cylinders can be installed with different size hydraulic connections.

For replacement, Schaeffler Automotive Aftermarket recommends two repair variants:

- Concentric slave cylinders with small connections (Fig. 1) were used in the original equipment. Depending on the vehicle assignment, these can be replaced by LuK part no.: 510 0088 10 or 510 0164 10
- A concentric slave cylinder with a large connection (Fig. 2) originates from a previous repair, whereby the hydraulic connection of the vehicle was converted. When installing LuK part no.: 510 0088 10 or 510 0164 10 the vehicle must be converted back to the small connection, i.e. a new hydraulic pipe must be fitted



Fig. 2: Concentric slave cylinder with large hydraulic connection

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264

Fax: +44 (0) 1432 375 760

aftermarket.uk@schaeffler.com

www.repxpert.co.uk